



## **INSTRUCTIONS FOR USE**

### **MIXING AND APPLICATION**

All surfaces to be treated with FS Screed should be clean, dry and roughened to provide a key. Dustfree shotblasting, scabbling, scarifying and planing are recommended methods of preparation for concrete, screed, asphalt, stone, wood and steel. Weak or friable surfaces should first be primed with WD Bonder to consolidate the base. Check that the preparation is complete. Mix WD Bonder by pouring the entire contents of the WD Bonder hardener container into the WD Bonder base container and mix thoroughly. Apply by brush or roller to the area to be treated with FS Screed, working to an area appropriate to the size of the units of FS Screed to be laid. Pour the entire contents of the FS Screed hardener container into the FS Screed base container and stir thoroughly until completely mixed. Add about half the contents of the FS aggregate bag to a forced action or cretriangle mixer and begin mixing. Whilst the aggregates are being blended add the previously mixed FS Screed into the aggregate mix and drain completely from the FS base container. Add the remaining aggregate to the mixing drum or pan and mix for approximately 2-3 minutes until the FS Screed is an even mortar consistency. Empty the mixed mortar onto the 'wet' primed WD Bonder and spread out evenly at the required thickness and trowel smooth with a steel trowel wiping the surface of the trowel with a damp cloth moistened with water. Never add water to the FS mortar mix or onto the surface of the FS Screed.

#### **Coverage and Pack Sizes**

<b>Pack Size (Kg)</b>	<b>Pack Size (Ltr)</b>	<b>Approx. Coverage</b>
25kg	12ltr	2.4m <sup>2</sup> @ 5mm
50kg	24ltr	4.8m <sup>2</sup> @ 5mm

### **DISPOSAL**

All tools and equipment should be cleaned with Conren Solvent Cleaner immediately after use. Spillage should be absorbed with sand or sawdust and disposed of in accordance with statutory regulations..

### **STORAGE**

Shelf life at least 12 months if stored in original containers between 10° C and 25° C

### **PRECAUTIONS**

For further information on our precautions please see the MSDS.

#### **Technical Service and Quality Assurance**

All information provided in this leaflet is based on results obtained from our own experience and testing which is given in good faith. The information is provided without guarantee as the user will be deemed to have satisfied themselves independently of the suitability of Conren's product for their own particular purpose. Conren Limited cannot be held responsible for any errors as a result of any incorrect information being provided.



**www.conren.com**

Conren Limited. Unit 1, The Bridge Business Centre,  
Ash Road South, Wrexham Industrial Estate,  
Wrexham. LL13 9UG

Tel: +44 (0) 1978 661 991  
Fax: + 44 (0) 1978 664 664  
E-mail: info@conren.com